TO BE FILLED BY THE INSPECTING OFFICER (ASSISTANT ENGINEER)

1 Name of Officer SONA O T

2 Name of School SRI SAI VIDYA BHAVAN

3 Location with Name of Educational District, : P Vemballur

Sub District

Irinjalakuda Educational District

Kodungallur Sub District

4 Classification buildings as specified in

Col.4 of the application for Fitness

Certificate & size

Permanent

separately attached

5 Period for which the certificate issued : Academic year 2025-26

6 Nature of defect if any

a) Foundation & basement : No

b) Superstructure : No

c) Doors and window No

d) Wood work wrought & put up : No

e) Roof : No

f) Flooring No

g) Miscellaneous (Cracks etc) : No

7 Any major defects noticed which will: No other defects

render the building unsafe

done properly

8 Whether maintenance works have been: Yes. Necessary safety precuations should

be taken for students.

9 Whether the structure is sound or not for : Sound for conducting classes under normal

conducting classes

weather and wind conditions.

Note: 1. The stability of the structure should be examined also with reference to location, attitude, intensity or wind, exposure to flood etc.

- 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate
- 3. Second floor of both Administrative Block and Main Block are not considered for issuing fitness as its Completion & Occupancy Certificate procedures are not completed yet.

Certified that the School was inspected by me on 29.05.2025 and found to be fit to Assistant Engli conduct classes for the academic year 2025-26 for the reasons stated above.

Place: Santhipuram

Date: 30.05.2025

Signature: Designation:

Sreenarayanapuram Grama Panchayat Ph: 9037528703, 04802850252